


## 88SE9230 bios burn update SOP

Note: Program tool have to run it on real DOS environment, not Windows DOS mode

1. Please unzip RE9230.A12.zip and copy RE9230.A12 folder to C:\
2. Boot into DOS
3. Please into C:\RE9230.A12
4. Type “ autoexec.bat ” to start update firmware
5. When screen shown Finish ! that's mean update finish and successful.



### Check new Firmware version

Please attached disk to 9230 HBA any port then power on PC and type Ctrl+M into 9230 HBA BIOS to check BIOS version :1.0.0.1024, Firmware Version: 2.3.0.1065