

Release Notes

Intel® Killer Performance Suite 40.25.509.1465

Supported Operating Systems

Microsoft Windows 10® and Windows 11® (64 Bit only)

Supported Products and Driver Versions

Intel® Wireless Adapter	Windows 10	Windows 11
Intel® Killer Wireless-AC 1550	23.140.0.3	
Intel® Killer Wi-Fi 6 AX1650		
Intel® Killer Wi-Fi 6e AX1675		
Intel® Killer Wi-Fi 6e AX1690		
Intel® Killer E3100 2.5Gb Ethernet	1.1.4.43	2.1.4.3
Intel® Killer E3100x 2.5 Gb Ethernet		
Intel® Killer E5000 Ethernet	10.74.1118.2024	1126.22.1118.2024
Killer E3000 2.5Gb Ethernet	10.73.815.2024	1125.22.1118.2024
Killer E3100G 2.5Gb Ethernet		
Killer E2500v2 1Gb Ethernet	10.73.815.2024	1168.22.1118.2024
Killer E2600 1Gb Ethernet		
Killer Networking Software	40.25.509.1465	

Note: This Software Release version does not include new drivers for the Killer E2200, Killer E2400, Killer E2500, Killer 1525 Wireless, Killer 1535 Wireless, Killer 1435 Wireless, or the Killer AX500 Wireless adapters, but the Killer Networking Software can be installed on the systems with the above adapters.

Corrected Customer Issues Installation

<i>Description of Key Issue</i>
Updated Wi-Fi driver to version 23.140.0.3
Killer Software: Package Version 40.25.509.1465

Note: Key issues fixed in the OS indicated on the table above

Known Issues

<i>Description of Key Issue</i>
[Killer 4.0] Crash occurred when click "GameFast" in Settings

Corrected Customer Issues – Killer Software: Package Version 40.25.509.1465

<i>Description of Key Issue</i>
'Auto' theme button set high contrast theme instead of Windows default theme
Clicking 'Start VR' started VR mode, but wasn't reflected by button change
Wi-Fi Analyzer did not present MLO Wi-Fi
Wi-Fi Analyzer did not switch correctly between 2.4 and 5 Ghz networks
Some buttons were not clearly visible in light mode because of font color

Note: Key issues fixed in the OS indicated on the table above

New added features – Killer Software: Package Version 40.25.509.1465

<i>Description of feature</i>
New UI redesign was made for easier navigation between all the features and to be compliant with all the new and upcoming requirements
Automatic Overclocking is a feature that allows you to quickly and easily enabling/disabling of overclocking capabilities of your computer.

Note: Key issues fixed in the OS indicated on the table above

Key Issues Fixed and Changes: Package Version 23.140.0.3

Description of Key Issue	OS
This software released version 23.140.0.3 has been updated to include functional and security updates. There may be other minor issues addressed which will impact performance, stability, or vendor specific functionality not listed above. <u>Users are encouraged to update to the latest version for best performance</u>	Win10/Win11

Note: Key issues fixed in the OS indicated on the table above

Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

©May 2025 Intel Corporation.