


August 2023



Release Notes

Intel® PROSet/Wireless Software 22.240.0

Supported Operating Systems

Microsoft Windows® 10 and Microsoft Windows® 11

Important Notice: Starting with Software Release 21.50.1, there will be no new driver versions for Windows*7 and Windows* 8.1 Operating Systems.

Supported Products and Driver Versions

Intel® Wireless Adapter	Windows® 10 Windows® 11	Windows* 8.1	Windows* 7
Intel® Wi-Fi 6E AX411 (Gig+)	22.240.0.6 ¹	n/a	n/a
Intel® Wi-Fi 6E AX211 (Gig+)			
Intel® Wi-Fi 6E AX210 (Gig+)			
Intel® Wi-Fi 6 AX203			
Intel® Wi-Fi 6 AX201			
Intel® Wi-Fi 6 AX200			
Intel® Wi-Fi 6 AX101			
Intel® Wireless-AC 9560			
Intel® Wireless-AC 9461/ 9462			
Intel® Wireless-AC 9260			
Intel® Dual Band Wireless-AC 3168	64-bit: 19.51.47.1 32-bit: 19.51.40.1 ²	19.10.21.1	19.10.21.1
Intel® Dual Band Wireless-AC 3165			
Intel® Wireless 7265 Family (Rev.D)			

¹ 64-bit only

² 32-bit drivers available for Windows® 10 will only receive updates to address potential security vulnerabilities from version 22.170.x package onwards. Last available Win10 32-bit driver version is 19.51.40.1 from package 22.160.0

Key Issues Fixed and Changes: Package Version 22.240.0

Description of Key Issue	OS
Rx link speed is not stable and wireless dock APP sometimes show "weak connection."	Win10/Win11
Beamformee report with VHT may cause fatal error resulting in yellow bang.	Win10/Win11



Description of Key Issue	OS
QoS with P2P connection may cause disconnect.	Win10/Win11
This software release version 22.240.0 has been updated to include functional updates. There may be other minor issues addressed which will impact performance, stability, or vendor specific functionality not listed above. Users should update to the latest version.	Win10/Win11

Legal Notices

No license (express or implied, by estoppel or otherwise) to any of Intel's intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors known as errata which may cause deviations from published specifications. Current characterized errata are available on request.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Performance varies depending on system configuration.

No computer system can be absolutely secure. Check with your system manufacturer or retailer or learn more at intel.com.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others

The Bluetooth® word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. and any use of such marks by Intel is under license.

©August 2023 Intel Corporation.

